

Metallurgy for the Blacksmith




Chart 8. Temperature scales and ranges of incandescent and tempering colors.